AMERICAN HOSE & HYDRAULICS
FULL SERVICE SUPER SHOPS

AMERICAN REFUSE SUPPLY
SANITATION TRUCK PARTS

2016 Mack last 7 of vin # M056758

U029D lost communication with NOx Sensor A

U029E " " " "
" B

P1140 Volvo Compression Brake (VCB) Control oil Temp. Too low

U010C Lost communication with Turbo Control Module A

P20B1 Reductant Heater Coolant Control Valve Control Circuit Gp

U02A82 Lost communication with Reductant Quality Module

639-5 J1939 Can Message

639-2 J1939 CCVS Timeout signal
639-2 Timeout data on ETC7 or VP15

www.americanhose.net

700 21st Ave. Paterson, NJ 07513 973-684-3225 Fax 973-684-3789
489 Henry St. Elizabeth, NJ 07207 908-527-9002 Fax 908-994-0977
30A Railroad Ave. West Haven, CT 06516 203-931-8545 Fax 203-931-9387
521 Longfellow Ave. Bronx, NY 10474 718-893-8157 Fax 718-617-1271

204-9	J1939	abnormal MID 136 update
205-9	J1939	" update
		MID 130
200-9	J1939	" "
		MID 128
207-9		" "
		Undefined
231-2		J1939 Data Link
		Erratic, Intermittent or
		Incorrect
231-2		J1939 Data Link
		" " "
		"